1969

2.07 6.5

DAVENPORT MACHINE CONDITION CHECK-LIST

DATE 1916 23MACHINE # D-04

INITIALS

CHECK AND RECORD MACHINE CONDITION

Ser (873)

ABC

		AB	-
1.	Clean and inspect mist collector	X	
	A. Remove filters and clean	X	
	B. Condition of belt Inchient Foll	X	
	C. Condition of motor	X	
	D. Condition of bearings	X	
	E. Condition of ionizer wires	X	
1.	Stud and Bushing in "C" position Swing Arm	X	
2.	Stud and Bushing in "E" position Swing Arm	X	
3.	Check gap between Revolving Head and Cap	*	
4.	Check for excessive end play of revolving head.	X	
5.	Check head locking and locating arm for the following conditions: Pin, bushings, head movement when locking, proper clearance between locating block and the lever, roll and pin.	X	
6.	Work Spindle Condition: Side play Spindle #1 Record (1002 - 1002) Spindle #2 Record (1002 - 1002) Spindle #3 Record (1002 - 1002) Spindle #4 Record (1002 - 1002) Spindle #5 Record (1002 - 1002)	×	
7.	"A" position cross slide	×	
8.	"B" position cross slide	X	
9.	Check feed mechanism	X	
10.	Check chuck opening mechanism	X	

FORM 020-80-20 Rev. 5 06/11/2021

11.	Check chuck closing mechanism	1
12.	Check tension of main drive and lube pump belts	X
13.	Inspect chuck and feed cam	X
14.	Lube System and Gauges:	7
	A. Remove and clean lube tank.	2
	B. Clean metal screens and replace pump filter	X
	C. Check pressure gauges	X
	D. Check pump operation and correct pressure	X
	E. Inspect lines and manifolds for damage and correct oil output as specified	X
	F. Drain and replace oil in worm housings	X
	G. Verify oil output at threading clutch manifold	7
15.	Inspect hand clutch	X

A = Acceptable

B = Repaired

C = Schedule for Repair Comments:

41300 Belt for mistedlecker

7446-74 - oil filter clement